


Reminder: Pin headers are missing from drawing as I usually remove them. Headers are usually sticking out to the front making it impossible to use effectively in a panel. Also, the TM1638 chip is mounted on the back. This is not shown.



JY-MCU TM1638 unit

Drawn: Steven Mackaay

Tolerances unless specified:

X.X	$\pm 0.06''$
X.XX	$\pm 0.01''$
X.XXX	$\pm 0.005''$
X.XXXX	$\pm 0.0005''$
Angles	$\pm 0.5^\circ$

All angles are in decimal degrees